



**S.B.G. (P-1500)****PowerMaster**

ITEM	QTY	DESCRIPTION	COMPUTER PART #	PARTS #	LIST \$
1	ONE	MAIN HOUSING WELDMENT		900	
2	ONE	COVER		901	
3	ONE	SIDE DOOR		987	
4	ONE	ARM CAP		902-1	
5	ONE	ELECTRICAL PLATE		970	
6	ONE	SWITCH PANEL		971	
7	ONE	LIMIT SWITCH MOUNTING BRACKET		973	
8	ONE	PRESSURE PLATE		1016	
9	ONE	ACCESSORY PLATE		969	
10	TWO	LOOP DETECTOR BRACKET		3704	
11	ONE	RADIO CONTROL BRACKET		968	
12					
13					
14	ONE	CLUSTER WELDMENT		1035	
15	ONE	DRIVE PLATE WELDMENT		1029	
16	ONE	DRIVE SHAFT WELDMENT		910	
17	ONE	INTERMEDIATE SHAFT WELDMENT		9705	
18					
19	ONE	UPPER CONTROL ARM		905	
20	ONE	DRIVE LINK		935	
21	FOUR	BRASS WASHER (SPACER)		936	
22	TWO	BEARING SPACER		941	
23	ONE	MOTOR PULLEY		AS2062	
24	ONE	3/16" SQUARE KEY		SK316X1.250	
25	ONE	3/16" SQUARE KEY		SK316X1.375	
26	TWO	1/4" SQUARE KEY		SK14X1.250	
27					
28					
29	ONE	5" "A" DRIVE SHEAVE		AS-5062	
30	TWO	CLUTCH DISC		1034CSW	
31	ONE	V-VELT		4L-220	
32	ONE	GEAR REDUCER		V.E.-55	
33	ONE	INTERMEDIATE SPROCKET		7313	
34	ONE	DRIVE ROLLER CHAIN		RC50X41	
35	TWO	1" FOUR BOLT FLANGE BEARING		UCF20516	
36	TWO	1-1/4" TWO BOLT FLANGE BEARING		UCFL20720	
37	THREE	LIMIT COLLAR		SC100-L	
38	FOUR	CLUTCH SPRING		C.120	
39	TWO	PLAIN BEARING		PBO-751050	

**S.B.G. (P-1500)****PowerMaster**

ITEM	QTY	DESCRIPTION	COMPUTER PART #	PARTS #	LIST \$
40					
41					
42	ONE	MOTOR		100802	
43	ONE	CONTROL BOARD (AS REQ'D)		BARCON1	
44	ONE	OR CONTROL BOARD/TIMER BOARD (AS REQ'D)		PRB3/ACT	
45	ONE	12 PIN WIRING HARNESS		12P-HARN	
46	ONE	2 AMP RESETTABLE FUSE		REY0022	
47	ONE	TRANSFORMER		TU1-2440VA	
48	ONE	14 POSITION TERMINAL STRIP		TS-114	
49	ONE	TIMER TOGGLE SWITCH		CB201-73	
50	ONE	ON/OFF SWITCH		2GK51-73	
51	ONE	OPEN/CLOSE SWITCH		6GM5B-78	
52	ONE	DOUBLE LIMIT SWITCH		LS-DAT-#6	
53	TWO	SINGLE LIMIT SWITCH		LS-AT#2	
54	ONE	1Ø OVERLOAD RESET SWITCH		MB-07	
55	TWO	STRAIGHT CONNECTOR		501-DC2	
56	TWO	4 PIN MALE CONNECTOR		4P-MCON	
57	TWO	4 PIN FEMALE CONNECTOR		4P-FCON	
58	ONE	9 PIN MALE CONNECTOR		9P-MCON	
59	ONE	9 PIN FEMALE CONNECTOR		9P-FCON	
60	ONE	4" SQUARE 15A, 120V INCOMING POWER SWITCH BOX W/OUTLET		V353D	
61	ONE	INTERLOCK SWITCH		IS#10	
62					
63					
64	FOUR	SOCKET SET SCREW		1404SSC	
65	ELEVEN	SOCKET SET SCREW		3105SSC	
66	FOUR	SQUARE HEAD SET SCREW		SQ51618X.625	
67	TWO	PAN HEAD MACHINE SCREW		0640MSP	
68	THREE	ROUND HEAD MACHINE SCREW		1406MSR	
69	EIGHT	FLAT SOCKET HEAD CAP BOLT		3220CSFL	
70	TWO	SOCKET HEAD CAP BOLT		5032CSP	
71	FOUR	CARRIAGE BOLT		1424C	
72	FOUR	CARRIAGE BOLT		3736C	
73	FOUR	CARRIAGE BOLT		5024C	
74	TWO	HEX HEAD TAP BOLT		1410BHT	
75	FOUR	HEX HEAD CAP BOLT		3724CH2	
76	FOUR	HEX HEAD CAP BOLT		5024CH2	
77	TWO	HEX WASHER HEAD MACHINE SCREW		0808MSW	

# S.B.G. (P-1500)

PowerMaster

ITEM	QTY	DESCRIPTION	COMPUTER PART #	PARTS #	LIST \$
78	TWO	HEX WASHER HEAD MACHINE SCREW (GREEN)		1106MSW	
79					
80	FOUR	HEX JAM NUT		37NJ	
81	EIGHT	HEX NUT		50NF	
82	TWO	SERRATED HEX FLANGE NUT		06NR	
83	TWO	SERRATED HEX FLANGE NUT		08NR	
84	TEN	SERRATED HEX FLANGE NUT		14NR	
85	FOUR	SERRATED HEX FLANGE NUT		31NR	
86	TWELVE	SERRATED HEX FLANGE NUT		37NR	
87	TWO	NYLON INSERT STOP NUT		50NS	
88	SIX	WING NUT		14NWC	
89					
90					
91	TWO	FLAT WASHER		06WSAE	
92	SIX	FLAT WASHER		14WSAE	
93	TWO	FLAT WASHER		50WSAE	
94	TWO	FLAT WASHER		75WSAE	
95					
96	TWO	LOCK WASHER		06WS	
97	SEVEN	LOCK WASHER		37WS	
98	EIGHT	LOCK WASHER		50WS	
99					
100	TWO	ROLL PIN		R218X100	
101	ONE	ROLL PIN		R375X200	
102	FIVE	PLASTIC STAND OFF		PSO-14	
103	EIGHT	RIVET		1624-0041	
104	ONE	LOCK CYLINDER ASSEMBLY		3795-6T	
105	ONE	PHENOLIC KNOB		HK-3816	
106	ONE	1/2" GROMMET		G-50	
107	THREE	7/8" GROMMET		G-87	
108					
109	ONE	ARM (LENGTH AS REQ'D)		912	
		"FOLLOWING PARTS ARE REQUIRED FOR			
		OPERATORS THAT REQUIRE COUNTER WEIGHTS"			
110	ONE	WEIGHT CARRIER BRACKET		811	
111	AS REQ	SINGLE COUNTER WEIGHT		9707	
112	AS REQ	DOUBLE COUNTER WEIGHT (NOT SHOWN)		9708	
113	AS REQ	HEX CAP BOLT		5064-CH2	
114	AS REQ	HEX NUT		50NF	

# S.B.G. (P-1500)

PowerMaster

ITEM	QTY	DESCRIPTION	COMPUTER PART #	PARTS #	LIST \$
115	AS REQ	LOCK WASHER		50WS	